

TABLE OF CONTENTS

Pre-Hurricane Image

Post-Hurricane Image

Zones

Berths, Jetties, and Tanks


Ships and Vehicles

Roof Damage

Site Flooding

Assessment Criteria

Buckeye Bahamas Hub | Pre-Hurricane



Buckeye Bahamas Hub | Post-Hurricane



Zones



Berths, Jetties, and Tanks




Berths, Jetties, and Tanks




Berths, Jetties, and Tanks



Ships and Vehicles




Roof Damage






Site Flooding





Site Flooding





Assessment Criteria

Tanks

- Smoke and/or fire
- Oil on ground
- Structural damage
- Missing covers or tops for Fixed Top tanks
- Oil above Floating Top tanks
- Debris around tank obviously from tank
- Displacement of entire structure

Jetties / Berths

- Smoke and/or fire
- Oil in water
- Structural Damage
- Debris in water obviously from jetty
- Displacement of entire jetty

•

Construction Materials

 New materials and associated equipment being brought to the site

Pipelines

- Smoke and/or fire
- Oil on ground or pipes
- Structural damage
- Debris around pipe obviously from pipe
- Oil seeping into water (submarine pipes)
- Displacement of pipe

Vehicles

- Count of employee cars
- Additional vehicles such as

Ships

Count of ships



Contact us for more information

Remote Sensing Metrics, LLC www.rsmetrics.com

New York:

Maneesh Sagar, CEO 646-504-7594 msagar@rsmetrics.com

Chicago:

Tom Diamond, President
312-282-4600
tdiamond@rsmetrics.com